

**Motor Driver IC Specification List**

<b>Product</b>	<b>Type</b>	<b>Supply Voltage</b>	<b>Output Voltage</b>	<b>Output Current</b>
<a href="#">L293</a>	Quad Half-H	4.5 to 36V	36V	600mA
<a href="#">L297</a>	Stepper Motor	4.7 to 7V	3.9V	10mA
<a href="#">L298</a>	Full Bridge	4.5 to 7V	46V	2A
<a href="#">SN754410</a>	Quad Half-H	4.5 to 36V	36V	1.1A